

25X1

**Page Denied**

NAVY Review Completed

On far side of oil line is a long  
transit shed. [ ] is still 25X1  
incomplete - the roof is on, it seems,  
only temporarily: rain drips through, etc.

These lines run above ground here, then go under  
ground at a point just this side of wall, designator L.

✓ Fresh water, good drinking, poor pressure.  
Faucet-type, 2 1/2" connection.  
15-20'

wooden platform above pipes - steps at  
end toward center of pier.

light poles - lighting termed "poor"

NAVY Review Completed

wooden guard house

concrete

light poles - lighting termed "poor"

wooden platform above pipes - steps at  
end toward center of pier

ramp bent over pipes

✓ Fresh water, good drinking, poor pressure.  
Faucet-type, 2 1/2" connection.

Vessel's berth - [ ]

25X1

Approved For Release 2009/08/03 : CIA-RDP80T00246A007500670002-4



Approved For Release 2009/08/03 : CIA-RDP80T00246A007500670002-4